

Auto Lensmeter

● Flip TFT Monitor


● Holder

● Lens Beveller

● Lens Sest


● Record Button

● Ink Tank




Featured

● Precise Dots Mark Device




Fine Material
Precise Assembly
Stable Quality
Long Durability

● Optional Mark Pen




Ink dip or Cartridge type No scratch Lens Surface
Better Effect of Marking Easy Operation

● Frame PH Measure




Put frame to monitor align optical center to the PD which previously taken in advance, then move up and down till the lines meet and get PH

● Hartman Mult Dot Measure Tech



150 dots of Hartman
High Speed CCD
Accurate Precise Measurement
No Abba compensation needed

● UV Tester



UV Test Result
Range from 0% to 100%

● Data Output

1 External USB and 1 RS232 interface, the data can be Synchronized/share with auto phoropter or other optical equipments

